

XV50, XV144, XV222 ASSEMBLY MANUAL ERRATA

Rev. C-2, January 23, 2008

THESE CHANGES MUST BE MADE TO THE MANUAL OR YOUR TRANSVERTER WILL NOT FUNCTION CORRECTLY

1. **Page 19, Parts Inventory, C12:** In the description, delete “10 pF (100)” and insert “15 pF (15)”. Change the part number to: “E530140”.
2. **Page 43, Left Column, Last Step:** After C12 delete “10 pF (100)” and insert “15 pF (15)”.
3. **Page 44, Left Column, Sixth Step:** Delete this step, “Remove the tuning slug from L19...”
(The tuning slug is left in L19).
4. **Page 51, Right Column, Last Step:** Add at the beginning of the step, “Remove paint overspray from around the screw holes in the inside surface of the side covers to ensure good electrical contact with the 2D fasteners.”